


Windows Flash Utility SOP v1.00

1. Please enter "WIN" folder.
2. Please double click "FLASH.exe".



3. The system will prompt a command window and select "Yes".




4. The system will prompt a confirm window, **please do NOT remove AC power and do NOT try to Power off system**, and select "Yes" to continue process.



5. System will auto Reboot to continue process.

6. Please wait BIOS update process.
7. After updating BIOS completely, system will auto Reboot.
8. When you see the LOGO, please press “Delete” to enter BIOS Setup Menu.
9. Change page to “Exit”.
10. Select “Load Setup Defaults” and press “Enter”. Select “Yes” to load default settings.



11. Select “Exit Saving Changes” and press “Enter”.
12. Select “Yes” to restart.

